

66

LETTER BALLOT

(Proposed) Recommended Practice: Receiver Performance Guidelines
May 21, 2004

The Technology Group on Distribution (T3) on April 7 approved the (Proposed) Recommended Practice: Receiver Performance Guidelines (Doc. T3-611) which is attached for your consideration.

Please mark your vote and return this ballot form before the four-week deadline of June 18, 2004.


Question 1: Should the (Proposed) Recommended Practice: Receiver Performance Guidelines (T3-611) be approved?

Yes No Abstain

Question 2: Shall the ATSC President, in consultation with the Chairman of T3-Technology Group on Distribution, be given "editorial privileges" on the approved document referenced above?

Yes No Abstain

Member Organization NAB

Signature:  Date 6/3/04

Editorial comments, or specific objections:

- Informative reference to A/53 s/b updated to A/53C in section 2.3.2, 4.5.2.3 and footnote 15.
- Add A/D to abbreviations = Analog/Digital converter (it is used 3 times, each with that meaning)
- The description of figure 3.2 should be on the same page as the figure.
- Section 4.3 last sentence: add left out word 'noise' so: "rtr...translator with poor phase noise performance."
- Table 4.2 and 4.3 put spaces before and after +/- i.e., the entry in first row of 4.2 would be "N +/- 2". Also generally the table column headings are not separated by the column lines. Add lines or center entries under headings to improve appearance
- In section 4.5.2.5 the letters NT appear. This abbreviation, SCS and IDE are not defined.
- In Annex B above Fig B.3 there is a missing space between 6 and dB. Above: B.7 missing space between 1 and dB; B.8 between 7 and dB, B.12 between 15 and dB (also in fig title); C.1 between -10 and dB; C.2 between -19 and dB.

Please return this ATSC Letter Ballot by June 18, 2004 to the ATSC
via fax 202-872-9161 or <mailto:ballot@atsc.org>.